

TSB # 323-0059  
Prince Castle  
355 East Kehoe Blvd  
Carol Stream, IL 60188  
Date 1/22/2018

Dear Customer,

In a going effort to ensure quality on our Genuine OEM Equipment we are Issuing a Technical Service Bulletin for our DCFT Toaster Series. This bulletin will cover the retrofit of the new DCFT Club Idler Pulley Assembly (OEM Part # 527-888s) that will be replacing discontinued Pulley Assembly (OEM Part # 527-818s) listed below. Please see detailed instructions below.

**\*\*Please note only units under the standard OEM 2 year warranty will be covered by Prince Castle for this repair\*\***

**Issue:**

Old rev Idler Pulleys could have reduced life span causing damage to the club drive belt. This could lead to the club section unable to rotate.

**Common Symptoms:**

- Club Drive Belt Has Reduced Life Span
- Club Section Does not rotate


**New Kit Part #'s:**

- 527-888s (Club Drive Idler Pulley – Assembly)



**Discontinued Part #'s:**

- 527-818s (Club Driver Idler Pulley – Assembly)



TSB # 323-0059  
Prince Castle  
355 East Kehoe Blvd  
Carol Stream, IL 60188  
Date 1/22/2018



**Units Effected:**

- DCFT unit with serial #'s Prior to LMMK226996X

**Procedure:**

Follow Instructional video below on how to retrofit your DCFT with OEM Kit Part # 527-888s. Please ensure components replaced are Genuine OEM Prince Castle Parts.

**\*\*Any aftermarket parts installed will void Prince Castle's standard 2 year warranty\*\***

[https://www.youtube.com/watch?v=ta8\\_oBsvaic](https://www.youtube.com/watch?v=ta8_oBsvaic)



Sincerely,

A handwritten signature in black ink, appearing to read 'Paul Svenningsen', written over a light blue background.

Paul Svenningsen

Technical Service Manager U.S.