

TSB # 228-0033
Prince Castle
355 East Kehoe Blvd
Carol Stream, IL 60188
Date 3/17/2017

3Wire,

To ensure on going reliability Prince Castle is issuing TSB # 228-0033 for our CBT-SB-NA-1PS.

Toasters Effectuated:

CBT-SB-NA-1PS


Serial #'s Effectuated:

All current Production until otherwise notified.


Issue:

Frame Bracket not bent at 90 degree angle. There is a possibility crew could pull conveyor past stop and pinch motor harness. When this harness extension gets pinched it fries Main PCB driver boards resulting in the conveyor not turning. To correct this issue please bend the bracket at 90 degree depicted below.

Correct



Incorrect



Sincerely,