

TSB # 842-0052
Prince Castle
355 East Kehoe Blvd
Carol Stream, IL 60188
Date 9/14/2017



Dear Customer,

In a going effort to ensure quality on our Genuine OEM Equipment, we are Issuing a Technical Service Bulletin for our UHC6PT-22MCDCE Series. This Technical Service Bulletin is being issued to communicate new list pricing structures for our new UHC Ribbon Cable kits. To see if a unit is eligible for this repair under warranty, or to get more in depth explanation of this kit change please refer to Technical Service Bulletin # 842-0040 (Issued 6/7/2017). Please note the significant list price reduction from previous ribbon cable kits to better minimize out of warranty customer impact. For any other inquiries, or questions regarding these kits please contact your respected Prince Castle Service Managers.

New Kit #'s and New List Pricing:

- 95-2041s (HARNESS, RIBBON CABLE, 10" W/COATING SINGLE)
 - *List Price = \$29.99 USD*
- 95-2042s (HARNESS, RIBBON CABLE, 18" W/COATING SINGLE)
 - *List Price = \$33.99 USD*
- 95-204142pk12s (HARNESS, RIBBON CABLE, 10" W/COATING 6 PACK & HARNESS, RIBBON CABLE, 18" W/COATING 6 PACK)
 - *List Price = \$155.00 USD*

Sincerely,

A handwritten signature in black ink, appearing to read 'Paul Svenningsen', written over a light blue horizontal line.

Paul Svenningsen
Technical Service Manager U.S.